

## Lee Engineering Company

2023 WEST WISCONSIN AVENUE • MILWAUKEE WISCONSIN 53201 • TELEPHONE (414) 933-2100

January 12, 1973

Larry Geller

Chuo-ku, Tokyo 104 Japan

Dear Mr. Geller:

We are writing in reply to your letter of inquiry of January 3, 1973 in regard to our flour mills.

Millet must be mixed with wheat to grind properly. Kernels are too small and will feed too fast and end result will be that mill overload. Operation at 100 volts, 50 cycle reduces output only and is not harmful to mill operation.

We feel that spare parts that may be needed would only be brushes and armature assemblies. Our parts price list enclosed to simplify ordering for whichever model or models you may choose.

Sincerely,

LEE ENGINEERING COMPANY

Robert A. Seng, Sales Manager

RAS/aiq

Encl.: Flour Mill Data